

Oil Field Environmental Incident Summary

Incident: 20140313154029 **Date/Time of Notice:** 03/13/2014 15:40

Responsible Party: Colt Trucking- Alejandro Joel LeBaron

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 3/6/2014 **Time Incident:** 09:30

Facility ID Number:

County: STARK

Twp: 139

Rng: 99

Sec: 9

Qtr:

Location Description: Froehlich 44-9TFH SE SE SEC 9-139N-99W. South of Belfield on County Rd 38.

Submitted By: Emily Richardson

Received By:

Contact Person: Kenley LeBaron
2501 4th Street W Unit 101
Dickenson, ND 58601

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 600 Feet

Distance Nearest Water Well: 0.7 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5	Gallons	5	Gallons		

Description of Other Released Contaminant:

Diesel fuel.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No risk. Spill contained.

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Spill was contained and the contaminated gravel was shoveled into three, 5-gallon buckets.

Wastes Disposal Location: Chimney Butte Environmental disposal in Fairfield, ND

Agencies Involved:

Updates

Date: 3/13/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This release impacted areas on a county road. Followup is necessary.

Date: 10/10/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10/10/14.

No sign of spill that occurred on County Road 38. No surface water in the area.

No followup is necessary.